lease be advised that any information provided on, and with, this Notice of Claim will be published in he Public Access area of the Erie County Water Authorities website which can be accessed by the ieneral Public.

NOTICE OF CLAIM FORM

ERIE COUNTY WATER AUTHORITY
295 MAIN STREET – ROOM 350
BUFFALO, NEW YORK 14203-2494
(716) 849-8465

Claimant(s) Name	Kim M. Doane		
Address	151 Dexter St., Tonawanda	Cell Phone #	—
Email Address	Madnet@roadrunner.com	Home Phone #	716- [redacted]

Accident / Damage / Injury Location	151 Dexter St., Tonawanda		
Date of Incident	unknown/repaired 1/27/22	Time of Incident	a.m. / p.m.
Police Contacted?	Yes / (No)	Police Report Taken?	Yes / (No)
Name of Police Agency	N/A		

PROPERTY DAMAGE CLAIMS ONLY
If this is not your property, give the name and address of the owner:

N/A if not applicable

Name	Kim M. Doane		
Address	151 Dexter St. Tonawanda	Zip Code	14150
Home Phone #	716- [redacted]	Work Phone #	716- [redacted]

PLEASE ATTACH ESTIMATES

Repair Estimates	$ I paid 308.93 for initial visit	$ I paid to Cellino 5,623.27 on 1/27/22 for repairs

PROPERTY DAMAGE ~~AND PERSONAL INJURY~~ WITNESSES

Name	Cellino Plumbing	Name	Bill Weir, Construction Inspector
Address	631 Bullis Road, Elma	Address	3030 Union Rd. Cheektowaga
Phone	716-675-1111	Phone	716·685-8298/cell 716 [redacted]

Attach copies of Medical bills once submitted to health insurance or automobile insurance.

ONLY PROVIDE COPIES OF THE MEDICAL BILLS. DO NOT PROVIDE MEDICAL RECORDS WITH THIS CLAIM FORM.

Claimant's Statement (please print legibly and be specific):

The kitchen drain was not draining properly and was making a gurgling sound. Drain cleaner did not work. Called Cellino Plumbing and the technician tried to clear it at the trap riser. He could only go so far and ~~then~~ Cellino sent another techician to do a camera inspection. They could only go up to the sidewalk so they then had to dig a trench to see what the problem was. After digging the trench they found the EC water main was placed on top of the clay tile ~~sewer~~ sewer which caused it to collapse. Cellino Plumbing called EC Water + Bill Weir, construction Inspector, came out and verified the EC water main caused the collapse of the tile sewer. Bill Weir spoke to me personally and gave me his card saying EC would send me this form to submit to be reimbursed ~~to~~ for my payment(s) to Cellino for their services. Bill Weir also said EC would take care of the cement work and final landscaping. I am attaching color photocopies ~~o~~ Cellino Plumbing took. I can send them by email or they can if you need them.

All statements herein are made under penalty of perjury.

Add Additional Pages if necessary

Date: 2/1/22

Kim M. Doane
Claimant's Signature

STATE OF NEW YORK)
COUNTY OF ERIE) ss:

On this 1st day of February 2022, before me personally appeared to me known, and known to me to be the same person described in and who executed the within instrument and he/she acknowledged to me that he/she executed the same.

Maureen B. Daly
Notary Public

MAUREEN B. DALY
Notary Public, State of New York
Reg #01DA4725820
Qualified in Erie County
My Commission Expires June 30, 2022